

**DELHI JAL BOARD: GOVT. OF NCT OF DELHI**  
**OFFICE OF THE EXECUTIVE ENGINEER (RWH/GWC)**  
**ROOM NO. 209, VARUNALAYA PHASE-I**  
**KAROL BAGH, NEW DELHI – 110005**  
**# 23558264**

No./DJB/EE(RWH/GWC)/2019/ 1751.

DATED: 11/04/19.

To,

Director Cum Manager,  
Balvantray Mehta Vidya Bhawan  
Anguridevi Shersingh Memorial Academy,  
Greater Kailash-II, New Delhi-110048

**Subject:-Regarding adequacy of rain water harvesting system at Balvantray Mehta Vidya Bhawan Anguridevi Shersingh Memorial Academy, Greater Kailash-II, New Delhi-110048.**

Sir/Madam,

The above said unit has been inspected by Joint Inspection Team on dated 09.04.2019, constituted by Hon'ble NGT in O.A. No. 217/2016. It was found that three Nos. RWH pit are existing at site.

The existing RWH structures are adequate to harvest the roof top run-off for catchment area of above said unit. The RWH structures are found to be functional at the time of inspection.

You are advised to keep the existing RWH system neat & clean & maintain the same periodically. Rain Water conveyance system shall be duly kept connected to RWH pits and filter media shall be maintained and kept neat & clean, as per DJB norms and over flow shall always remain connected to municipal drain.



EE (RWH/GWC)

EE (G W CELL)  
DELHI JAL BOARD  
VARUNALAYA BHAWAN,  
JHANDEWALLAN, N.D.-05

